Oil Field Environmental Incident Summary

Responsible Party: Wisco PRD **Well Operator:** WISCO, INC.

Well Name: Wisco PRD

Field Name: WILLISTON Well File #:

 Date Incident:
 7/20/2016
 Time Incident:
 10:30
 Facility ID Number:
 700090-01

 County:
 WILLIAMS
 Twp:
 154
 Rng:
 104
 Sec:
 26
 Qtr:
 NW NE

Location Description:

Submitted By: Donald Plew Received By:

Contact Person: Donald Plew

15495 Highway 2 Williston, ND 58801

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 1 Mile

Distance Nearest Water Well:

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - On Facility Site Reported to NRC: No

Oil 8			
OII	Barrel	ls 8	Barrels
Brine 2:	2 Barrel	le 22	Barrels

Other

Description of Other Released Contaminant:

Cuillad Unita

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

None - No LEL, NO H2S, NO CO, No caustic chemicals, just saltwater and oil

Areal Extent:

Followup Units

Potential Environmental Impacts:

None - all contained within berm and no more than 4" of soil saturation

Action Taken or Planned:

Spill was stopped when operator noticed leak. Contained within berm on class 5 soil. Hydrovac was called out to remove impacted soil. No tenorm issues so soil will be put in East building on pad, and dried out. All standing fluid has been or will be sucked up with pump in plant or by hydrovac and put back into tanks.

Wastes Disposal Location: After drying, recovered soil will be sent to Wisco landfill. Liquids will be put in tanks at PRD and processed.

Agencies Involved:

Updates

Date: 7/21/2016 Status: Reviewed - Assigned to Other Agency Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release remained on location according to the report. NDIC retains oversight.